



Status for OY-BBW - Piper PA28-180 - s/n 28-2737

NEXT MAINTENANCE DUE AT HOURS/DATE: 5703 / 15-3-2014

DK.MG.1005 Sign.

X = Mangel på info

----- = Ej udfyldes

Actual time: 5688.00.00		Actual Cycles		0,0		Warning:		hours	days					
Actual Tacho								50,0	360					
Date: 09/09/13						Accomplished / Installed		Next due inspection						
Item Name / Maintenance	Part Number	Serial Number	Approved, TBO/LIFE	Hours	Ext. %	Years	Normal due hours	Actual perf. hours	Actual perf. Date	Normal due hours	Extendet due hours	Date	TACHO	Comments
Piper 50 hrs. Inspection	230-207		50H	50	10		5.688,0	5688,0		5.738,0	5.743,0	-----		pilot owner maintenance
Piper 100 hrs. Inspection	230-207		100H	100	10	1	5.603,0	5603,0	15/03/13	5.703,0	5.713,0	15/03/14		
Piper Special Inspections:	01/31/08									-----	-----	-----	-----	
Flap internal inspection			200H	200	10		5.634,0	5634,0		5.834,0	5.854,0	-----	-----	
Valve rocker inspection			400H	400	10		5.527,0	5527,0		5.927,0	5.967,0	-----	-----	
Fuel selector valve insp.			400H	400	10	1	5.603,0	5603,0	15/03/13	6.003,0	6.043,0	15/03/14	-----	
Flush oil radiator			500H	500	10		5.613,0	5603,0		6.113,0	6.163,0	-----	-----	
Slick magneto inspection			500H	500	10		5.634,0	5634,0		6.134,0	6.184,0	-----	-----	
Replace cowling teflon bushings			500H	500	10		5.254,0	5254,0		5.754,0	5.804,0	-----	-----	
Clean & lubricate trim drum screw			500H	500	10		5.254,0	5254,0		5.754,0	5.804,0	-----	-----	
MLDG torque link greaser bolt inspection			500H	500	10		5.254,0	5254,0		5.754,0	5.804,0	-----	-----	
Replace oil cooler hoses			1000H/8Y	1.000	10	8	5.634,0	5634,0	18/07/13	6.634,0	6.734,0	18/07/21	-----	
Replace engine compartment hoses			1000H/8Y	1.000	10	8	4.873,0	4873,0	23/11/06	5.873,0	5.973,0	23/11/14	-----	
Aircraft structure inspection			2000H/7Y	2.000	10	7	5.254,0	5254,0	21/12/09	7.254,0	7.454,0	21/12/16	-----	
Engine Overhaul	O-360-A3A	L-8319-36A	2000H/12Y	2.000	20	12	5.113,0		10/09/08	7.113,0	7.513,0	10/09/20		
Alternator Overhaul			2000H	2.000			5.254,0	5254,0		7.254,0	7.254,0	-----		
Propeller Overhaul	76EM8S5-0-60	103016K	2000H/10Y	2.000		10	5.634,0	5634,0	18/07/13	7.634,0	7.634,0	19/07/23		
Wing spar inspection			62900H-6000H	62.900						62.900,0	62.900,0			
Static pressure and altimeter insp./test			2 Y			2			13/01/12	-----	-----	26/03/14	-----	
Transponder test			2 Y			2			13/01/12	-----	-----	26/03/14	-----	
Magneto overhaul LH	4373	13010487	2000H/12Y	2.000		12	5.634,0	5634,0	18/07/13	7.634,0	7.634,0	18/07/25		
Magneto overhaul RH	4370	13030716	2000H/12Y	2.000		12	5.634,0	5634,0	18/07/13	7.634,0	7.634,0	18/07/25		
Forward muffler			1000H	1.000	10		5.254,0	5254,0		6.254,0	6.354,0	-----		
Rear muffler	66894-03		1000H	1.000	10		5.175,0	5175,0		6.175,0	6.275,0	-----		
Clean & lubricate all exterior bearings			1000H	1.000	10		5.254,0	5254,0		6.254,0	6.354,0	-----		
Inspect condition of hinge bolts			1000H	1.000	10		5.254,0	5254,0		6.254,0	6.354,0	-----		
Check upper nose gear bearing			1000H	1.000	10		5.254,0	5254,0		6.254,0	6.354,0	-----		
Dry air pump wear inspection	AA3215CC	02V301	500H-100H/1Y	500	10		5.634,0	5634,0	15/03/13	6.134,0	6.184,0	-----		
Fuel tank/wing spar corrosion inspection			7Y		10	7		4732,0	21/12/09	-----	-----	21/12/16		
Replace fuel tank hoses			7Y		10	7			21/12/09	-----	-----	21/12/16		



Status for OY-BBW - Piper PA28-180 - s/n 28-2737

NEXT MAINTENANCE DUE AT HOURS/DATE: 5703 / 15-3-2014

DK.MG.1005 Sign.

X = Mangel på info
----- = Ej udfyldes

		Actual time:	5688.00.00	Actual Cycles				0,0		Warning: hours days				
		Actual Tacho								50,0	360			
		Date:	09/09/13							Accomplished / Installed			Next due inspection	
Item Name / Maintenance	Part Number	Serial Number	Approved, TBO/LIFE	Hours	Ext. %	Years	Normal due hours	Actual perf. hours	Actual perf. Date	Normal due hours	Extendet due hours	Date	TACHO	Comments
Fluid hoses test - fuselage & wings			10Y		10	10			21/12/09	-----	-----	22/12/19		
Hydrostatically test fire extinguisher			12Y		10	12			21/12/09	-----	-----	21/12/21		
Replace fluid hoses - fuselage & wings			20Y		10	20			21/12/09	-----	-----	22/12/29		
National requirements/inspections:														
First aid kit			1 Year			1			15/03/13	-----	-----	15/03/14		
Fire Extinguisher Halon			1 Year			1			15/03/13	-----	-----	15/03/14		
Compass deviation			1 Year			1			15/03/13	-----	-----	15/03/14		
Engine BL 1-1 internal inspection	O-360-A3A	L-8319-36A	10Y / 5Y		10	10			18/07/13	-----	-----	19/07/23		
Weight & Ballance			5Y		10	5			13/05/11	-----	-----	12/05/16		
Airworthiness Review Certificate			1Y			1			15/03/13	-----	-----	15/03/14		
Life jacket			10Y			10			30/11/06	-----	-----	30/11/16		
ELT	406 PLB XS3	252362				6			31/03/09	-----	-----	31/03/15		
Repetitive AD notes:														
FAA AD 69-22-2	control wheel		100H	100			5.603,0	5603,0		5.703,0	5.703,0	-----		
FAA AD 95-26-13	oil cooler hose		100H/1Y	100		1	5.634,0	5634,0	18/07/13	5.734,0	5.734,0	18/07/14		
FAA AD 2004-10-14	crankshaft gear		OH/prop strike	2.000	20	12	5.113,0	5113,0	19/06/08	7.113,0	7.513,0	19/06/20		
FAA AD 2013-02-13	stabilator control	SB 1245A	2000H/7Y	2.000		7	5.603,0	5603,0	15/03/13	7.603,0	7.603,0	15/03/20		
EASA AD 2005-0023R2	exh. valve guide		1000H	1.000			5.113,0	5113,0	10/09/08	6.113,0	6.113,0	-----		
EASA AD 2005-0032	wing main spar		7Y			7			21/12/09	-----	-----	21/12/16		
EASA AD 2005-0034	stabilator tube		200H	200			5.634,0	5634,0	18/07/13	5.834,0	5.834,0	-----		
EASA AD 2005-0035	cast main ldg.		100H	100			5.603,0	5603,0		5.703,0	5.703,0	-----		
Repetitive Service Bulletins:														
Piper SB 251D	fule tank insp.		100H	100	10		5.603,0	5603,0		5.703,0	5.713,0	-----		
Lycoming SB 366B	carb. body screw		100H	100	10		5.603,0	5603,0		5.703,0	5.713,0	-----		
Lycoming SB 582A	carb. over floating		50H/1Y	50	10	1	5.688,0	5688,0	25/07/13	5.738,0	5.743,0	25/07/14		pilot owner maintenance
Piper SB 1244	aft wing attach insp.		2000H/7Y	2.000		7	5.653,0	5653,0	15/03/13	7.653,0	7.653,0	15/03/20	-----	